

Product Safety Recall

Lightforce LiFePO₄ Battery Charger Power Cords with Missing Earth Pins


Some Lightforce 170mm Handheld Lights with LiFePO₄ batteries and some Lightforce LiFePO₄ Battery Chargers supplied between January 2014 and May 2018 may include power cords that do not have an earth pin.

The missing pin does not pose a risk for users of the battery charger but could result in an electrical shock causing serious injury or death if the power cord is used with another 240V appliance that requires an earth pin.

Consumers or stockists who purchased the following products should stop using the affected power cord immediately and contact Lightforce Customer Service on 1800 03 03 08 to arrange a return and replacement.

Up to 1,042 individual units of the following products may be affected:

**LIGHTFORCE 170MM LIGHTS
WITH LIFEPO4 BAG PACKS
(WALK170HIDLIFE, WALK170LIFE,
WALK170LIFEVP), LIGHTFORCE
BATTERY KITS & CHARGERS
(BP7LIFE, BCLP7-2, CBLP6,
CBLP9C, CBLPBC), & POWER
CORDS (LPLEADAU).**



This pin may be missing on some power cords.

See productsafety.gov.au for
Australian product recall information